

AD-A106 167

PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. BENSON LAKE DAM (MO 30667), MISSOU--ETC(U)
SEP 80 W G SHIFRIN

F/G 13/13

DACW43-80-C-0094

NL

UNCLASSIFIED

1 OF 2
AL
AD-00000



AD A106167

LEVEL 2

①

MISSOURI - KANSAS CITY RIVER BASIN

BENSON LAKE DAM
GASCONADE COUNTY, MISSOURI
MO. 30667

DTIC
ELECTE
OCT 27 1981
S E

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

DTIC FILE COPY



United States Army
Corps of Engineers

...Serving the Army
...Serving the Nation

St. Louis District

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved
for public release and sale; its
distribution is unlimited.

SEPTEMBER, 1980

81 10 26 090

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A106 167	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Benson Lake Dam (MO 30667) Gasconade County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Consoer, Townsend and Associates, Ltd.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0094
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Corps of Engineers		12. REPORT DATE September 1980
		13. NUMBER OF PAGES Approximately 125
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) National Dam Safety Program. Benson Lake Dam (MO 30667), Missouri - Kansas City River Basin, Gasconade County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

412553



REF ID:
ATTENTION ON

DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD NORTH
ST. LOUIS, MISSOURI 63101

SUBJECT: Benson Lake Dam Dam (Mo. 30667) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Benson Lake Dam (Mo. 30667).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood
- 2) Overtopping could result in dam failure
- 3) Dam failure significantly increases the hazard to loss of life downstream

SUBMITTED BY: _____
Chief, Engineering Division Date

APPROVED BY: _____
Colonel, CE, District Engineer Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

BENSON LAKE DAM
GASCONADE COUNTY, MISSOURI

MISSOURI INVENTORY NO. 30667

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY
CONSOER, TOWNSEND AND ASSOCIATES, LTD.
ST. LOUIS, MISSOURI
AND
PRC ENGINEERING CONSULTANTS, INC.
ENGLEWOOD, COLORADO
A JOINT VENTURE

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

SEPTEMBER 1980

3

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Benson Lake Dam, Missouri Inv. No. 30667
State Located: Missouri
County Located: Gasconade
Stream: An unnamed tributary of the Frene Creek
Date of Inspection: April 24, 1980

Assessment of General Condition

Benson Lake Dam was inspected by the engineering firms of Consoer, Townsend and Associates, Ltd. and PRC Engineering Consultants, Inc. (A Joint Venture) of St. Louis, Missouri according to the U. S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District of the Corps of Engineers. Based upon the criteria in the guidelines, the dam is in the high hazard potential classification, which means that urban development with more than a small number of habitable structures could be affected in the event of failure of the dam. Within the estimated damage zone of three miles downstream of the dam are one dwelling, four buildings, two trailers, an oil depot, sewage lagoons and a state highway (Hwy 100) which may be subjected to flooding, with possible damage and/or destruction, and possible loss of life. Benson Lake Dam is in the small size classification since it is less than 40 feet in height and impounds less than 1000 acre-feet of water.

In general, the dam appears to be in poor condition. Our inspection and evaluation indicates that the spillway of Benson Lake Dam does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Benson Lake Dam being a small size dam with a high hazard potential is required by the guidelines to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood without overtopping. Considering the number of inhabited dwellings, a state highway, and an oil depot being located downstream of the dam, the PMF is considered the appropriate spillway design flood for Benson Lake Dam. It was determined that the reservoir/spillway system can accommodate approximately 20 percent of the Probable Maximum Flood without overtopping the dam. Our evaluation also indicates that the reservoir/spillway system can accommodate the one-percent chance flood (100-year flood) without overtopping.

The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region.


Another major deficiency with Benson Lake Dam is the three scarps observed on the downstream slope on the left side of the embankment and the seepage observed in the area. Two of the scarps were fairly shallow and approximately 3-feet wide. The other scarp was approximately 20-feet wide at the top and 30 feet wide at the bottom. These scarps and the seepage indicate instability of the slope.

Other deficiencies noted by the inspection team were the minor wave erosion on the upstream slope, the trees on the upstream and the downstream embankment slopes, the tall vegetation on the embankment, rodent activity on the embankment, the erosion on the left side slope of the spillway channel, tall grass growing within

2


the spillway channel, a need for periodic inspection by a qualified engineer and a lack of maintenance schedule. The lack of seepage and stability analyses on record is also a deficiency that should be corrected.

It is recommended that the owner take immediate action to study the embankment seepage and stability problem and correct or control the several deficiencies described above in the near future.



Walter G. Shifrin, P.E.





Overview of Benson Lake Dam

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

BENSON LAKE DAM, I.D. No. 30667

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	3
	1.3 Pertinent Data	7
SECTION 2	ENGINEERING DATA	9
	2.1 Design	9
	2.2 Construction	9
	2.3 Operation	9
	2.4 Evaluation	9
SECTION 3	VISUAL INSPECTION	11
	3.1 Findings	11
	3.2 Evaluation	18

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES	20
	4.1 Procedures	20
	4.2 Maintenance of Dam	20
	4.3 Maintenance of Operating Facilities	20
	4.4 Description of Any Warning System in Effect	21
	4.5 Evaluation	21
SECTION 5	HYDRAULIC/HYDROLOGIC	22
	5.1 Evaluation of Features	22
SECTION 6	STRUCTURAL STABILITY.	27
	6.1 Evaluation of Structural Stability.	27
SECTION 7	ASSESSMENT/REMEDIAL MEASURES.	30
	7.1 Dam Assessment	30
	7.2 Remedial Measures.	33

TABLE OF CONTENTS
(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP	1
PLAN AND SECTIONS OF DAM	2
GEOLOGIC MAPS	3-4
SEISMIC ZONE MAP	5

APPENDICES

APPENDIX A	-	PHOTOGRAPHS
APPENDIX B	-	HYDROLOGIC AND HYDRAULIC COMPUTATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

BENSON LAKE DAM, Missouri Inv. No. 30667

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for Benson Lake Dam was carried out under Contract DACW 43-80-C-0094 between the Department of the Army, St. Louis District, Corps of Engineers, and the engineering firms of Consoer, Townsend & Associates, Ltd., and PRC Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of Benson Lake Dam was made on April 24, 1980. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project, presents a summary of visual observations made during the field inspection, presents an assessment of hydrologic and hydraulic conditions at the site, presents an assessment of the structural adequacy of the various project features and assesses the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing and detailed analyses were not within the scope of this study. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that in this report reference to left or right abutments is viewed as looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to the west abutment or side, and right to the east abutment or side.

d. Evaluation Criteria

The inspection and evaluation of the dam is performed in accordance with the U.S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District office of the Corps of Engineers for Phase 1 Dam Inspection.

1.2 Description of the Project

a. Description of Dam and Appurtenances

The following description is based upon observations and measurements made during the visual inspection and from conversations with Wilbur Benson, a representative of the owner. Design drawings were not located for the dam or appurtenant structures.

The dam is an earthfill structure between earth abutments. The crest has a total length of 277 feet between the spillway and the right abutment. The maximum crest elevation is approximately 712 feet above mean sea level (MSL) at a point 100 feet to the right of the spillway. The crest elevation drops 6 inches from this point to the spillway and 2 feet from this point to the right abutment. The dam has a somewhat curved alignment convex in the downstream direction. The crest width is 12 feet. The maximum height of the embankment from the downstream creekbed is approximately 25 feet. The upstream slope was measured to be 1 vertical to 3 horizontal (1V to 3H) from the crest to the water surface. The downstream slope was measured to be 1V to 2H. No riprap was provided as slope protection on the upstream slope.

The spillway is constructed into the left abutment and functions as an open channel. The approachway provides a smooth transition from the lake to the spillway channel. Once over the crest the invert slope is approximately 1%. The crest area cross-section is trapezoidal in shape with a 68 foot top width and a 45 foot bottom width. The channel bottom has a small subchannel at its invert which carries most of the flow for normal conditions; this subchannel is four inches deep with a 5 foot top width. The spillway channel has a 1.5

foot drop about 100 feet downstream from the crest. Approximately 50 feet downstream from the drop the alignment has a sharp curve to the right before it empties into the downstream channel. There is about 50 feet of channel between the sharp curve and the downstream channel. Downstream from the 1.5 foot drop, the slope of the invert increases and the width of channel decreases.

The right rim of the reservoir is parallel to a road and both the rim and the road are at a lower elevation than the top of dam. Before the dam could be overtopped, water would spill over this right rim and into the roadway. This condition causes the right reservoir rim especially at the right abutment to serve as an emergency spillway. The roadway at the right abutment is approximately 2.5 feet lower than the top of dam at its maximum section, whereas the spillway crest is almost 4 feet lower than the top of dam elevation at its maximum section.

There are no low level drains or mechanically controlled outlet works provided for this dam.

b. Location

Benson Lake Dam is located in in the State of Missouri, Gasconade County, and crosses an unnamed tributary to Frene Creek, which is tributary to the Missouri River. The damsite is approximately five miles southwest of Hermann, a community on the Missouri River, and can be found on the 7.5 minute series of the Hermann, Mo. Quadrangle Sheet in Section 15 of Range 5 West and Township 45 North.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams" by the U.S. Department of the Army, Office of the Chief Engineer, the dam is classified in the dam-size category as being "small" since its storage is less than 1,000 acre-feet. The dam is also classified as "Small" in the dam-size category because its height is less than 40 feet. The overall size classification is therefore "Small".

d. Hazard Classification

The dam has been classified as having a "High" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. Our findings concur with this classification. Within the estimated damage zone, which extends approximately three miles downstream of the dam, are one dwelling, four buildings, two trailers, an oil depot, sewage lagoons, and a state highway.

e. Ownership

Benson Lake Dam is owned privately by Mr. Clifford Benson. The mailing address is Mr. Clifford Benson, R.R. 1, Box 82, Hermann, Missouri 65041.

f. Purpose of Dam

The purpose of the dam is to impound water for recreational use as a private lake.

g. Design and Construction History

According to a neighbor, Mr. A.C. Schneider, the dam was built in 1966 (est.) by Mr. Glennon Epple of Hermann, Missouri. Efforts to contact the original builder were futile.

Mr. Elmer Kuhn, who was the soil conservationist for the Hermann, Missouri area, assisted with the initial planning for the dam. However, the dam wasn't built according to Mr. Kuhn's recommendations. The height of the dam and spillway were raised and the spillway width was decreased. The local Soil Conservation Service office doesn't have any records concerning Benson Lake. Benson Lake Dam was originally called Schneider Lake Dam.

h. Normal Operational Procedures

The dam is used to impound water for recreational use. Normal procedure is to allow the lake to remain as full as possible with the water level being controlled by rainfall, runoff, evaporation and the elevation of the spillway crest.

1.3 Pertinent Data

a. Drainage Area (square miles): 0.23

b. Discharge at Damsite

Estimated experienced maximum flood (cfs): 300

Estimated ungated spillway capacity with
reservoir at top of dam elevation (cfs): 338

c. Elevation (feet above MSL)

Top of dam (minimum): 710

Spillway crest: 708.2

Normal Pool: 708.2

Maximum Experienced Pool 710-

Observed Pool: 708.2

d. Reservoir

Length of pool with water surface
at top of dam (minimum) elevation (feet): 1000

e. Storage (Acre-Feet)

Top of dam (minimum) 20

Spillway crest: 14

Normal Pool: 14

Maximum Experienced Pool: 20-

Observed Pool: 14

f. Reservoir Surfaces (Acres)

Top of dam (minimum): 4.4

Spillway crest: 3

Normal Pool: 3

Maximum Experienced Pool: 4+

Observed Pool: 3

g. Dam

Type:	earthfill
Length:	227 feet
Structural Height:	25 feet
Hydraulic Height:	25 feet
Top width:	12 feet
Side slopes:	
Downstream	1V to 2H
Upstream	1V to 3H (crest to water surface)
Zoning:	Unknown
Impervious core:	Unknown
Cutoff:	Unknown
Grout curtain:	Unknown

h. Diversion and Regulating Tunnel None

i. Spillway

Type:	Trapezoidal open channel, uncontrolled
Length of crest:	45 feet (Bottom width)
Crest Elevation (feet above MSL):	708.2

j. Regulating Outlets None

SECTION 2: ENGINEERING DATA

2.1 Design

Design drawings or calculations are not available for the dam.

2.2 Construction

The dam was built by Mr. Glennon Epple of Hermann, Missouri. No construction records or data are available relating to the construction of the dam.

2.3 Operation

No operational records or data are available for the dam.

2.4 Evaluation

a. Availability

No design drawings, design computations, construction data, or operation data are available.

In addition, no pertinent data were available for review of hydrology, spillway capacity, flood routing through the reservoir, slope stability, seepage analyses, or foundation conditions.

b. Adequacy

The lack of engineering data did not allow for a definitive review and evaluation. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing and evaluating design, operation and construction data, but is based primarily on visual inspection, past performance history, and sound engineering judgement.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity

No valid engineering data are available.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the Benson Lake Dam was made on April 24, 1980. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Dr. M.A. Samad	PRC Engineering Consultants, Inc.	Project Engineer, Hydraulics and Hydrology
Mark R. Haynes	PRC Engineering Consultants, Inc.	Soils and Mechanical
Robert G. McLaughlin	PRC Engineering Consultants, Inc.	Civil
Razi Quraishi	PRC Engineering Consultants, Inc.	Geology
John Lauth	Consoer, Townsend & Assoc., Ltd.	Civil and Structural
Mr. Wilbur Benson	Representative of the Owner	

Specific observations are discussed below.

b. Dam

The dam crest supports an unmaintained vegetative cover which appears to be adequate protection against surface erosion. A comprehensive inspection of the crest was hampered due to the growth of vegetation. The curvature in the alignment and the crown in the crest do not appear to be due to an instability in the embankment. The dam was probably constructed this way. There was no evidence of significant settlement on the crest. No significant deviations in horizontal or vertical alignment were apparent. According to Mr. Wilbur Benson, the dam has never been overtopped and no evidence was observed indicating the contrary.

The upstream slope has no riprap protection. Some minor erosion due to wave action has occurred near the water surface. The slope above the water surface is adequately protected against surface erosion by a good growth of vegetation. No erosion gullies due to surface runoff were observed. Two trees were observed on the slope near the spillway. A comprehensive inspection of the slope was hampered due to the growth of vegetation. No settlements or bulges which would indicate an instability of the slope were apparent.

The downstream slope has a heavy growth of unmaintained vegetation which appeared to be adequate protection against surface erosion. No erosion due to surface runoff was observed. Considerable amount of trees were growing on the slope. In one area from approximately 50 feet to 100 feet to the right of the spillway, three scarps were observed. Two of the scarps were fairly shallow and approximately 3-feet wide. The other scarp was approximately 20-feet wide at the top and

30-feet wide at the bottom. The scarp extends from the toe of the dam to within 5 feet of the crest. The slope near the top of the scarp was near vertical. According to Mr. Benson, this area has been this way since 1977 when the Benson's took ownership of the property. Some indications indicate that the slough occurred fairly recently. The leaning of the young trees toward the slope in the area indicate that the slough had occurred fairly recently, however, grass has grown back on the steep sections of the scarp. Although seepage was observed on the slope in the area of the scarps, it was not possible to measure the flow rate for this investigation. Cattails were observed in the area which indicates that water (seepage) is present most of the time. No other depressions, bulges or cracks which would indicate an instability of the embankment were apparent on the slope.

Rodent activity was observed on the embankment. Several one inch diameter rodent holes were observed on the crest and the upstream slope. One large rodent hole was observed on the downstream slope. It was approximately 6 inches in diameter.

A small natural drainage channel was observed just downstream of the toe of the dam. The channel runs parallel to the embankment from the right abutment to the discharge channel of the spillway. The channel appeared to be used to drain the surface runoff of the right abutment area. Some flowing water was observed in the channel; however, it was not possible to determine whether or not this flow was due at least in part to seepage through the embankment or foundation.

Both abutments slope gently upward from the crest. No erosion which would affect the safety of the embankment or appurtenant structures was observed on either abutment. No seepage or instabilities which would affect the safety or stability of the dam were apparent on either abutment. The left abutment supports the spillway and the right abutment supports a gravel access road which runs perpendicular to the embankment. Rock outcrops were observed in the spillway discharge channel and on the right abutment.

c. Project Geology and Soils

(1) Project Geology

The damsite is located on an unnamed tributary of the Frene Creek in the Salem Plateau section of the Ozark Plateaus Physiographic Province. Deep dissection of topography by major streams is one of the important characteristics of the Salem Plateau section. There is a wide distribution of dolomites and limestones in the Salem Plateau. Cuestaform topography is exhibited in this plateau section, consisting of two major escarpments, namely the Crystal Escarpment and Burlington Escarpment. Deep dissection in dolomites and limestones is a major factor in the development of many springs in this area. The topography in the damsite vicinity is rolling to hilly with U to V shaped valleys. Elevation ranges from 927 feet above M.S.L. (nearly 0.5 miles northwest of the damsite) to 700 feet above M.S.L. at the Benson Lake. The reservoir slopes are generally 5° to 18° from horizontal. The reservoir appears to be watertight and free of any potential slide activity. The area at the damsite is covered with slope wash deposits of glacial-fluvial and loess in origin. These deposits consist of reddish-brown silty clay.

The inlet and outlet areas of the unnamed tributary of Frene Creek contain Quaternary Alluvium. Outcrops of Ordovician moderately weathered, hard Dolomitic rocks, horizontally interbedded with brown *Calcareous sandstones* and light gray shales, with a strike of N50E are exposed at the base of the spillway cut and at the downstream channel of the spillway. Each unit of these rocks is three feet thick, with horizontal to blocky joint pattern.

The areal bedrock geology beneath the slope wash deposits as shown on the geologic map of Missouri (1979), Plate 3 consists of Pennsylvanian rocks undifferentiated, Ordovician St. Peter's sandstone and Ordovician Dolomitic rocks. No faults have been identified in the vicinity of the damsite. The closest trace of a fault is the Cuba Fault nearly 22 miles south of the damsite. The Cuba Fault had its last movement in post-Pennsylvanian time. *This fault appears to have no effect on the damsite.*

Benson Lake Dam consists of an homogeneous earth-fill embankment and a spillway located at the right abutment end of the embankment. No boring logs or construction reports were available which would indicate foundation conditions encountered during the dam construction. It is assumed that the embankment probably rests on brownish-gray *Calcareous sandstone* interbedded with shales and dolomites. The spillway is cut into hard sandstone interbedded with shales and dolomites. The spillway rockcut slopes are relatively stable. Minor localized rock debris were observed at the foot of the slope at the downstream channel walls of the spillway.

(2) Project Soils

According to the "Missouri General Soil Map and Soil Association Descriptions" published by the Soil Conservation Service, the materials in the general area of the dam belong to the soil series of Gerald-Union-Goss in the Ozarks family. The soils were basically formed from loess and cherty limestone residuum. The permeability of these soils range from moderate to very slow.

Materials removed from the embankment on the upstream and downstream slopes approximately 1 foot below the vegetative cover appeared to be a light brown silty fine to medium sand. Based upon the Unified Soil Classification System, the soil probably be classified as a SM. This soil type generally has the following characteristics: semipervious to impervious with a coefficient of permeability less than 100 feet per year; medium to high shear strength; and a low to intermediate resistance to piping.

d. Appurtenant Structures

(1) Spillway

The banks of the spillway channel especially the left bank appear to be of easily erodible material as there are several erosion gullies forming along the slope. Although the channel is clear at the inlet area, the bottom of channel, a short distance downstream, becomes heavily laden with tall grass, bushes, and even a sapling or two. The bottom of channel seems to be in easily erodible soil also but, in an area where a rock outcropping occurs. There is much evidence of the erosion and rock downstream of the drop where the invert slope increases causing higher velocities. Sloughing

also seems to be present in this downstream portion. The entire bottom of channel is in bedrock through the sharp turn to the right and on down to the downstream channel.

(2) Outlet Works

There is no level drain or outlet works provided for this dam.

e. Reservoir Area

The water surface elevation was 708.2 feet above MSL on the day of the inspection. The reservoir rim is lined with trees along the right side which is also where a road runs adjacent to the reservoir. The remainder of the reservoir rim has mild grassy slopes. The slopes above the reservoir rim are mild and grass covered. The forested area begins a few hundred feet away from the reservoir rim. At least three drainage swales from the surrounding forest empty into the reservoir. There are no houses or other structures built in close proximity to the reservoir.

f. Downstream Channel

The downstream channel is well defined. The channel is 5 feet wide and 3 feet deep and has a side slope of 1V to 2H on the right side and 1V to 5H on the left side in the proximity of the damsite. Some trees and tall vegetation were observed growing on the channel. The trees and the tall vegetation will reduce the hydraulic efficiency of the channel.

3.2 Evaluation

The visual inspection did reveal one item which was significant enough to possibly warrant immediate remedial action. The scarps observed on the downstream slope indicate instability of the slope. The slope appeared to be stable at the time of the inspection, however, the potential of further sloughing of the slope is still there. The seepage observed in the area is also detrimental to safety and stability of the embankment. The seepage increases the potential for further failure in this area. The potential of the embankment to fail in this area is also increased if the dam is overtopped, the slope would probably erode faster in this area thus increasing the potential of failure. The embankment is also weaker in this area and the surcharge of water on the embankment as the reservoir level rises above the spillway crest could cause the embankment to fail.

The following conditions were observed which could affect the safety of the facility and will require maintenance within a reasonable period of time.

1. The minor wave erosion on the upstream slope does not appear to affect the stability of the dam in its present condition. Nevertheless, continual erosion of the slope could be detrimental to the stability of the dam.

2. The trees observed on the downstream and the upstream slopes pose a potential danger to the safety of the dam depending upon the extent of the root system. The roots of trees present possible paths for piping through the embankment. The root systems can also do damage to the embankment from being uprooted by a storm.

3. Rodent activities observed on the embankment could jeopardize the safety of the dam. The holes created by the animals make avenues for possible piping.

4. The vegetation on the embankment should be properly maintained. A heavy growth of vegetation on the embankment hinders a comprehensive inspection of the dam and potential problems could go undetected.

5. Although the spillway area does not seem to be in a condition that jeopardizes the safety of the dam, the following conclusions seem likely: (a) the erosion through the left bank will get worse and soil will be washed downstream if left in the "as is" condition, (b) the tall grass etc. growing within the channel slows the velocity of the flow thus causing some backwater effects, and (c) the channel banks downstream of the drop will continue to erode and slough into the bottom of channel.

6. If water overflows the roadway at the right abutment and flows down along the upstream right abutment contact, problems could arise due to a weakening between the dam and the abutment.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

Benson Lake Dam is used to impound water from rainfall and runoff for recreation. The water level below the spillway crest is allowed to remain as high as possible.

4.2 Maintenance of Dam

The dam is maintained by the owner, Mr. Clifford Benson, and his brother, Mr. Wilbur Benson. The maintenance of the dam appears to be inadequate. The downstream slope is covered with dense vegetation, bushes, saplings and trees and on the upstream slope a few small trees and saplings are growing.

There is an erosion gully at the downstream side of the spillway. This erosion should be arrested before it can do any damage to the embankment.

There have not been any major repairs done to the dam since its original construction.

4.3 Maintenance of Operating Facilities

There are no operating facilities associated with this dam.

4.4 Description of Any Warning System in Effect

The inspection team is not aware of any existing warning system in effect.

4.5 Evaluation

The maintenance at Benson Lake Dam appears to be inadequate at this time. The remedial measures described in Section 7 should be undertaken to improve the condition of the dam.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The watershed area of Benson Lake Dam upstream from the dam axis consists of approximately 147 acres. There is an upstream dam above Benson Lake Dam. The watershed area between the upstream dam and Benson Lake Dam investigated in this report is about 93 acres. Most of the watershed area is wooded with some range and pasture land. Land gradients in the watershed average roughly 7 percent. Benson Lake Dam is located on an unnamed tributary of Frene Creek. The reservoir is about 2-1/4 miles upstream from the confluence of the unnamed tributary and Frene Creek. At its longest arm the watershed is approximately 0.8 mile long. A drainage map showing the watershed, the downstream hazard zone, and location of the upstream dam is presented as Plate 1 in Appendix B.

Evaluation of the hydraulic and hydrologic features of Benson Lake Dam was based on criteria set forth in Corps of Engineers' "Engineer Regulation No. 1110-2-106", and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based on criteria given in EM 1110-2-1411 (Standard Project Storm). The SCS method was used for deriving the unit

hydrographs, utilizing the Corps of Engineers' computer program HEC-1 (Dam Safety Version). Two unit hydrographs were derived. One unit hydrograph was for the drainage above the Upstream Dam; another unit hydrograph was for drainage area between the Upstream Dam and Benson Lake Dam. The SCS method was used for determining loss rate. The hydrologic soil group of the watershed was determined by use of published soil maps. The hydrologic soil group of the watershed and the SCS curve number are also presented in Appendix B. The curve number, the unit hydrograph parameters, and the PMP rainfall were directly input to the HEC-1 (Dam Safety Version) computer program to obtain the PMF hydrograph. The computed peak discharges of the PMF and one-half of the PMF at the Upstream Dam reservoir are 1159 cfs and 579 cfs respectively. The peak discharges of the PMF and one-half of the PMF for the area between the Upstream Dam and Benson Lake Dam are 2026 and 1013 cfs respectively. Both the PMF and one-half of the PMF inflow hydrographs at the Upstream Dam were routed through the Upstream reservoir by the Modified Puls Method, also utilizing the HEC-1 (Dam Safety Version) computer program. A storm of 50 percent and 25 percent PMF, respectively, preceded the PMF and 50 percent PMF by four days. The reservoir was assumed at the mean annual high water level at the beginning of the antecedent storm. The mean annual high water level for the Upstream Dam was estimated to be at the crest of the spillway. The antecedent 50 percent PMF storm, when routed through the reservoir will leave the reservoir at the same elevation as the spillway crest at the end of four day period. Thus the reservoir was assumed at the crest level of the spillway at the start of the routing computation for PMF, one-half of the PMF and other PMF ratio floods. The failure elevation of the upstream dam was set at the minimum elevation of the top of dam. The breach dimension for the upstream dam was determined according to the guidelines furnished by the St. Louis Dis-

trict Corps of Engineers.

The peak outflow discharges with dam break for the PMF and one-half of the PMF at the Upstream Dam are 1091 cfs and 578 cfs, respectively. Both the PMF and one-half of the PMF when routed through the reservoir resulted in overtopping of the Upstream Dam. The outflow hydrographs at the Upstream Dam were routed through the channel between the Upstream Dam and Benson Lake Dam and then were combined with the PMF and one-half of the PMF hydrographs for Benson Lake Dam. The combined hydrographs for both the PMF and one-half of the PMF, were then routed through Benson Lake Dam reservoir. The reservoir was assumed at mean annual high water level at the beginning of the routing computation. The mean annual high water level for Benson Lake Dam Reservoir was estimated to be at the crest of the spillway. The peak outflow discharges for the PMF and one-half of the PMF at Benson Lake Dam are 2,887 cfs and 1,340 cfs, respectively. Both the PMF and one-half of the PMF, when routed through the reservoir resulted in overtopping of Benson Lake Dam.

The sizes of physical features utilized to develop the stage-outflow relation for the spillway and overtopping of the dams were prepared from field notes and sketches prepared during the field inspection. The reservoir elevation-area data were obtained from the U.S.G.S. Hermann, Missouri Quadrangle topographic map (7.5 minute series). The spillway and dam overtop-rating curve and the reservoir elevation-area curve for Benson Lake Dam are presented as Plates 2 and 3 in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam must aim at avoiding overtopping. Overtopping is especially dangerous for an earth dam because of its erodable characteristics. The safe hydrologic design of an embankment dam requires a spillway discharge capability combined with an embankment crest height that can handle a very large and exceedingly rare flood without overtopping.

The Corps of Engineers designs dams to safely pass the Probable Maximum Flood that could be generated from the dam's watershed. This is generally the standard for dam safety where overtopping would pose any threat to human life. Accordingly, the hydrologic requirement for safety for this dam is the capability to pass the Probable Maximum Flood without overtopping.

b. Experience Data

It is believed that records of reservoir stage or spillway discharge are not maintained for this site. However, according to Mr. Wilbur Benson, the maximum reservoir level was about a few inches above the roadway at the right abutment.

c. Visual Observations

Observations made of the spillway during the visual inspection are discussed in Section 3.1d(1) and evaluated in Section 3.2.

d. Overtopping Potential

As indicated in Section 5.1.a, both the Probable Maximum Flood, and one-half of the Probable Maximum Flood when routed through the reservoir, resulted in overtopping of the dam. The peak outflow discharges for the PMF are 2,887 and 1,340 cfs, respectively. The maximum capacity of the spillway just before overtopping the dam is 338 cfs. The PMF overtopped the dam by 2.33 feet and one-half of the PMF overtopped the dam by 1.35 feet. The total duration of overflow over the top of dam is 5.25 hours during the PMF and 1.17 hours during one-half of the PMF. The spillway/reservoir system of Benson Lake Dam is capable of accommodating a flood equal to approximately 20 percent of the PMF just before overtopping the dam. The reservoir/spillway system of Benson Lake Dam will accommodate the one-percent chance flood without overtopping.

The surface soils in the embankment and the spillway appear to be a sand-silt mixture. The dam is overtopped by over 2 feet during the occurrence of the PMF. The maximum velocity of flow in the spillway during the PMF will be about 8 ft/sec, which exceeds the permissible velocity (5 ft/sec) in the spillway. The dam itself would be susceptible to erosion due to high velocity of flow on its downstream slope, specially in the area of the scarps observed on the downstream slope, during overtopping of the dam.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

The evidence of the past sloughing and the present seepage observed on the downstream slope indicates a serious instability and potential for failure of the embankment in the area of the observed scarps. Seepage was observed in the area of the scarps. The scarps and the seepage observed on the slope indicate instability of the slope. The minor erosion of the upstream slope due to wave action was not serious enough to constitute an unsafe condition. Nevertheless, the erosion should be monitored and if the erosion continues, steps should be taken to control the problem. No other major signs of settlement or distress were observed on the embankment or foundation during the visual inspection. In the absence of seepage and stability analyses, no quantitative evaluation of the structural stability can be made.

The spillway crest area and the channel appear to be generally stable albeit in poor condition. The roadway, which will act as emergency spillway also appears to be in a stable condition.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available. No embankment or foundation soil parameters were available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction were available for use in a stability analysis.

c. Operating Records

No operating records are available relating to the dam or appurtenant structures. No regulated outlet works was provided for the dam. The water level on the day of the visual inspection was at the crest of the spillway. According to Mr. Wilbur Benson, the reservoir remains close to full at all times.

d. Post Construction Changes

No post construction changes are known to exist which will affect the structural stability of the dam.

e. Seismic Stability

The dam is located in Seismic Zone 1, as defined in "Recommended Guidelines For Safety Inspection of Dams" as prepared by the Corps of Engineers, and will not require a seismic stability analysis. An earthquake of the magnitude which would be expected in Seismic Zone 1 will not cause distress to a well designed and constructed earth dam.

Available literature indicates that no active faults exist near the vicinity of the damsite.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation, however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based upon observations of field conditions at the time of inspection along with data available to the inspection team.

It is also important to note that the condition of a dam depends upon numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be assurance that an unsafe condition could be detected.

a. Safety

The spillway capacity of Benson Lake Dam is found to be "Seriously Inadequate". The spillway/reservoir system will accommodate about 20 percent of the PMF without overtopping the dam. The surface soils in the embankment and the spillway appears to be a sand-silt mixture. The dam is overtopped by over 2 feet during the occurrence of the PMF. The maximum velocity of flow in the spillway during PMF will

be about 8 ft/sec. The velocity in the spillway will thus exceed the permissible velocity of 5 ft/sec (Kentucky Blue Grass-sandy silt). The dam would also be susceptible to erosion due to high velocity of flow on its downstream slope, due to overtopping of the dam during the occurrence of the PMF.

No quantitative evaluation of the safety of the embankment can be made in view of the absence of seepage and stability analyses. The present embankment, however, has reportedly performed satisfactorily since its construction without failure or evidence of instability, except for instability of the left side of the downstream slope. Reportedly, the dam has never been overtopped and there was no evidence indicating the contrary.

The safety of the dam can be improved if the deficiencies described in Sections 6.1a and 3.2 and below are properly corrected as described in Section 7.2. The trees observed on the downstream and upstream slopes pose a potential danger to the safety of the dam depending upon the extent of the root system. The roots of trees present possible paths for piping through the embankment. The root systems can also do damage to the embankment from being uprooted by a storm. Therefore, the trees should be removed from the embankment under the guidance of an engineer experienced in the design and construction of earthen dams.

The existence of burrowing animals on the embankment could jeopardize the safety of the dam. The holes created by the animals make avenues for possible piping. The extent of damage to the embankment done by the burrowing animals should be determined and corrective measures undertaken as required.

The spillway system seems to be functioning in a reasonably efficient manner and doesn't pose any hazards for the dam. The roadway at the right abutment, which will act as emergency spillway, was once overflowed during a flood. The roadway seems to be in good condition.

b. Adequacy of Information

Information relating to the design and construction of the dam is lacking. The conclusions presented in this report are based upon field measurement, past performance and present condition of the dam. Information on the design hydrology, hydraulic design, and the operation and maintenance of the dam were not available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency

The steepness (almost vertical) of the scarps observed on the downstream slope, in conjunction with the seepage observed at the base of the scarps, poses a potential instability of the embankment, which should be investigated in the immediate future. The remaining remedial measures recommended in Section 7.2 should be accomplished within a reasonable period of time.

d. Necessity for Phase II Inspection

Based on results of the Phase I inspection, a Phase II inspection is not felt to be necessary. However, the remedial measures described in Paragraph 7.2 should be undertaken within the time frame recommended in Section 7.1(c).

7.2 Remedial Measures

a. Alternatives

There are several general options that may be considered to reduce the possibility of dam failure or to diminish the harmful consequences of such a failure. Some of these options are:

1. Increase spillway capacity to pass the Probable Maximum Flood without overtopping the dam.
2. Increase the height of the dam enough to pass the PMF without overtopping the dam. An investigation should also be done that includes studying the effects on the structural stability of the existing embankment and the spillway. The overtopping depth during the occurrence of the PMF, stated in Section 5.1d, is not the required or recommended increase in the height of the dam.
3. A combination of 1 and 2 above.

b. O & M Procedures

1. Perform an investigation of the stability and safety of the embankment due to the scarps and the seepage observed on the downstream slope.
2. The erosion due to wave action on the upstream slope should be monitored and if the erosion continues, protective measures should be employed to protect the slope from further damage.

3. Remove the trees from the downstream and upstream slopes of the dam. Removal of large trees should be under the guidance of an engineer experienced in the design and construction of earthen dams.
4. Determine the extent of damage done to the embankment by burrowing animals, and corrective repairs made as required. All burrowing animals should be eliminated from the embankment and their burrows properly backfilled and compacted.
5. The vegetation on the embankment should be properly maintained and an adequate vegetative cover retained on the embankment to protect it from surface erosion. A heavy growth of vegetation on the embankment could prevent a comprehensive inspection of the dam and potential problems could go undetected.
6. If during periods of spillage over the roadway at the right end of the dam, the water flows down the right upstream abutment contact area, a permanent berm should be constructed in order to direct this flow to a point beyond the abutment contact area and downstream toe. Once the flow is downstream from the abutment contact area and the toe of the dam, it may be directed towards the downstream channel.
7. The entire spillway should be watched and checked periodically for progressive erosion and sloughing which would be seriously detrimental to its proper functioning. If these things do occur, remedial action should be taken.


8. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of earth dams.

9. The owner should initiate the following programs:



(a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams.

(b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.



PLATES



LOCATION MAP - BENSON LAKE DAM
MO. 30667




SCALE:
1" = 60' HORIZ.
VERT. - NOT TO SCALE



**BENSON LAKE DAM (MO. 30667)
PLAN AND SECTIONS**

LEGEND

<u>PERIOD</u>	<u>SYMBOL</u>	<u>DESCRIPTION</u>
QUATERNARY	Qal	ALLUVIUM: SAND, SILT, GRAVEL
	Pu	PENNSYLVANIAN UNDIFFERENTIATED
PENNSYLVANIAN	Pm	MARMATON GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
	Pcc	CHEROKEE GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
MISSISSIPPIAN	Mm	ST LOUIS FORMATION: LIMESTONE INTERBEDDED WITH SHALE.
		SALEM FORMATION: LIMESTONE INTERBEDDED WITH SHALE AND SILTSTONE
		WARSAW FORMATION: ARGILLACEOUS LIMESTONE AND CALCAREOUS SHALE
	Mo	KEOKUK - BURLINGTON FORMATION: CHERTY GRAYISH BROWN SANDY LIMESTONE
DEVONIAN	D	CHATTANOOGA SHALE, SYLAMORE SANDSTONE
ORDOVICIAN	Omk	MAQUOKETA SHALE, KIMMSWICK LIMESTONE
	Odp	DECORAH FORMATION: GREEN TO GRAY CALCAREOUS SHALE WITH THIN FOSSILIFEROUS LIMESTONE
	Osp	ST. PETER SANDSTONE
	Ojc	SMITHVILLE FORMATION POWELL DOLOMITE



APPENDIX A

PHOTOGRAPHS




PHOTO INDEX
FOR
BENSON LAKE DAM

Benson Lake Dam

Photographs

- Photo 1 - Top of dam showing tall grass protection.
- Photo 2 - Upstream slope of dam showing dense grass protection with a tree and some small brush growing.
- Photo 3 - Downstream slope of dam showing dense grass protection adjacent to slope supporting trees and brush.
- Photo 4 - View of sloughed area on downstream slope of dam, supporting growth of cattail reeds; indicated continuous moisture condition.
- Photo 5 - View of sloughed area adjacent to area in photo 4.
- Photo 6 - View of very wet ground just below sloughed areas of photos 4 and 5.
- Photo 7 - View of hole indicating possible burrowing activity on downstream slope area.
- Photo 8 - Reservoir rim area showing adjacent road and mild grassy and tree-lined slopes.
- Photo 9 - Inlet to principal spillway showing small amount of rock slope protection.
- Photo 10 - Principal spillway channel showing brush, fence, sloughing, erosion, and dense grass growth.
- Photo 11 - Downstream channel area showing tree-lined banks and structure.

Photo 12 - Structures in area downstream of dam.

Photo 13 - Geology--Ordovician dolomite, horizontal, interbedded with brown, calcareous sandstone.

Photo 14 - Geology--Ordovician brown to light grey shale, interbedded with calcareous sandstone.

Benson Lake Dam



Photo 1



Photo 2

Benson Lake Dam




Photo 3



Photo 4

Benson Lake Dam



Photo 5




Photo 6

Benson Lake Dam



Photo 7



Photo 8

Benson Lake Dam




Photo 9



Photo 10

Benson Lake Dam



Photo 11




Photo 12

Benson Lake Dam



Photo 13






Photo 14

APPENDIX B

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

PLATE I, APPENDIX B



CONTOUR INTERVAL 10 FEET
DATUM IS MEAN SEA LEVEL

DRAINAGE BOUNDARY - - - - -




BENSON LAKE DAM MO 30667

DRAINAGE BASIN

B-2

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI
 BENSON LAKE DAM #30667
 SLOTTED SPILLWAY RATING CURVE
 SHEET NO. 1 OF 5
 JOB NO. 1263
 BY FZ DATE MAY 80



B-3

PRC ENGINEERING CONSULTANTS, INC.

DESIGN OF INLET / MISSOURI

SHEET NO. 2 OF 5

BENEFIT LAKE


30667

JOB NO 1263

SMITHSONIAN OVER THE FALLING CURVE

BY FZ DATE MAY 80

Spillway channel



$$P = \frac{B + 2Y}{3} = 5.3 \text{ ft}$$

$$A = \frac{14}{9} \text{ sq ft} = 1.6 \text{ sq ft}$$

$$\text{Slope of channel} = \frac{10}{1200} = 0.0083$$

$$n = 0.03 \text{ assumed}$$

$$Y \leq 3 \quad A = Y(3.83Y + 45) + 1.6$$

$$P = 45.3 + 7.26Y$$

$$\frac{1.47 \times 5^{5/2}}{n} = \frac{1.47 \times 10.0033}{0.03} = 4.53$$

$$Q = 4.53 \frac{A^{5/3}}{P^{2/3}}$$

$$T = 45 + 7.67Y$$

$$Y > 3 \quad A = 68Y - 33$$

$$P = 6Y$$

$$\frac{1.47 \times 5^{5/2}}{n \cdot P^{2/3}} = 0.27$$

$$Q = 0.27 A^{5/3}$$

$$T = 68$$

$$Y_c = \sqrt{\frac{A^3 g}{T}}$$

Y_c	Q_c	Y_{NORMAL} for $Q = Q_c$	Remark
1'	280	1.16'	Subcritical
2'	303	2.17'	"
3'	1540	3.10'	"
4'	2542	4.05'	"
5'	3702	4.95'	Supercritical

PRC ENGINEERING CONSULTANTS, INC.

DAM SHEET: INLET / MICHIGAN SHEET NO 3 OF 5
 KENSON LAKE DAM # 20667 JOB NO 1263
 SPIED AND CORRECTED BY J. C. R. E. BY FZ DATE MAY 80

Length required to go from critical depth to normal depth.

$$\Delta L = \frac{Y_N - Y_c}{0.0082 - \frac{N^2}{1.48 A_m R_m^{4/3}}} \cdot \frac{V_c^3}{V_N^3} \cdot \frac{N}{D} \cdot A_m R_m^{4/3} = \frac{\Delta_m^{5/3}}{T_m^{2/3}}$$

Y_c	Y_N	A_c	A_N	V_c^3	V_N^3	A_m	P_m	Q	N	D	ΔL
1	1.16	50.453	58.95	3.479	0.35	54.70	53.85	280	0.031	0.002	16'
2	2.17	106.44	117.31	0.887	0.737	112.13	61.81	808	0.020	0.0011	18'
3	3.10	171.12	177.45	1.258	1.103	174.54	69.46	1540	0.005	0.0008	6'

conclusion the normal depth regime will be reached in a short distance and normal depth is to be considered for depth below 5'

PRC ENGINEERING CONSULTANTS, INC.

I AM SAFE / MISSOURI

SHEET NO. 4 OF 5

LEMON LAKE TRIM #3667

JOB NO 1263

SWILLING & OVERTOP RATING CURVE

BY FZ DATE MAY 80



$$\textcircled{2} \quad d_{c_1} \leq 2 \Rightarrow \begin{cases} d_{c_3} = \frac{1}{2} H_3 \\ T_2 = \frac{177 d_{c_3}}{2} \end{cases} \quad \begin{cases} A_3 = \frac{177 d_{c_3}}{4} \\ A_2 = 177 (d_{c_3} - 1) \end{cases}$$

$$\begin{aligned} t_2 &= t_1 - \frac{d}{c} \\ d_{c_2} &= d_2 + \frac{1}{2} \times \frac{1}{2} = \frac{81_{1/2} - 1}{12} \\ t_2 &= \sqrt{t_1^2 - d_{c_2}^2} = 25(4d_1 - 1) \\ \psi_2 &= \frac{f \cdot \Delta \theta}{\frac{1}{T}} = 0.57 A_2 \frac{\lambda}{c} \end{aligned}$$

Spillway ①						②						③			
Y_1	A_1	F_1	T_1	Q_1	$(\frac{F}{A})^{1/3}$	H_1	$\frac{H_2}{H_1-3}$	d_{c2}	A_2	Q_2	$\frac{H_2}{H_1-1.5}$	d_{c3}	T_2	A_3	Q_3
1	50.4	53.2	—	640	0.50	1.30	—	—	—	—	—	—	—	—	—
2	66.9	61.1	—	702	0.67	2.67	—	—	—	—	1.17	3.44	82.8	38.8	150
3	171.1	69.1	—	1418	1.07	4.07	1.07	0.80	54.7	229	2.57	2.05	177	185.3	1076
4	231.0	69.1	—	2473	1.66	5.66	2.66	1.86	160.7	1156	4.16	3.11	177	372.9	3071
5	327.0	—	68	3702	2.16	7.20	4.26	2.92	267.3	2480	5.76	4.17	177	561.7	5678
6	375.0	—	68	4947	2.76	8.76	5.76	3.92	367.3	3995	7.26	5.17	177	738.7	8563

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY / MISSOURI

SHEET NO. 5 OF 5


BERNARD LAKE DAM #30667

JOB NO. 1263

SPILLWAY & OVERTOP RATING CURVE (Cont'd)

BY FZ

DATE MAY 82



Assumed critical depth

$$A_4 = 41Y_4 - 4.25$$

$$T_4 = 41'$$

$$V_4 = \sqrt{\frac{A_4 g}{T_4}}$$

$$Q_4 = A_4 V_4$$

$$\frac{V_4^2}{2g} = \frac{A_4}{2T_4}$$

$$H_4 = Y_4 + \frac{V_4^2}{2g}$$

By iteration we have to find Q_4 for $H_4 + 1 = H_1$ (pg. 10)


$$WSEL = 708.5 + H_1$$

1	H_1	Y_4	A_4	$\frac{V_4^2}{2g}$	H_4	Q_4	$Q_1 + Q_2 + Q_3 + Q_4$	WSEL
1	1.3	0.258	5.73	0.092	0.30	14	233	709.80
2	2.67	1.148	46.02	0.522	1.67	248	1100	711.17
3	4.07	2.031	81.07	0.989	3.07	647	3370	712.57
4	5.47	2.912	124.57	1.511	4.66	1232	7932	714.16
5	6.87	3.798	168.08	2.052	6.26	1934	13794	715.76
6	8.26	4.678	209.28	2.552	7.76	2683	20238	717.26

$$y = 0.5$$

$$A = y(17y + 24)$$

$$T = 34y + 24$$




BENSON LAKE DAM (MO. 30667)
SPILLWAY & OVERTOP RATING CURVE
B-8

FORM 4

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION - MISSOURI SHEET NO. 1 OF 1
 DAM NAME: BENSON LAKE DAM / ID NO.: 30661 JOB NO. 1263
 RESERVOIR ELEVATION AREA DATA BY FE DATE MAY 80

ELEV. (M.S.L.) (Fe.)	RESERVOIR SURFACE AREA (Acres)	REMARKS
710	0	Assumed bottom of lake
710	0.5	Interpolated.
718	3	- Assumed Spillway Crest
704.5	4	- Roadway acting as emergency spillway
712	5	- High point of dam
720	11	- Measured on USGS QUAD.
730	17	- Interpolated.
740	22	- Measured on USGS QUAD



BENSON LAKE DAM (MO. 30667)
 RESERVOIR ELEVATION - AREA CURVE
 B-10

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 1

DAM NAME: PENNSYLVANIA LAKE DAM # 30667

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY FZ DATE 5/22/80

- 1) DRAINAGE AREA, $A = 0.145$ sq. mi. = (72.5 acres)
- 2) LENGTH OF STREAM, $L = (0.15 \text{ " } \times 2000' = 1400') = 0.36$ mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,
 $H_1 = 810'$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST, $H_2 = 711.2$
- 5) ELEVATION OF CHANNEL BED AT $0.85L$, $E_{85} = 780$
- 6) ELEVATION OF CHANNEL BED AT $0.10L$, $E_{10} = 715$
- 7) AVERAGE SLOPE OF THE CHANNEL, $S_{AVG} = (E_{85} - E_{10}) / 0.75L = \frac{780 - 715}{0.75 \times 1400} = 0.046$
- 8) TIME OF CONCENTRATION:

A) BY KIRPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = \left[\frac{11.9 \times 0.36^3}{810 - 711.2} \right]^{0.385} = 0.136 \text{ hr.}$$

B) BY VELOCITY ESTIMATE,

$$\text{SLOPE} = 5\% \Rightarrow \text{AVG. VELOCITY} = 4 \text{ fps.}$$

$$t_c = L/V = \frac{1400'}{4} \times \frac{1}{3600} = 0.132 \text{ hr.}$$

$$\text{USE } t_c = 0.136 \text{ hr.}$$

$$9) \text{ LAG TIME, } t_L = 0.6 t_c = 0.6 \times 0.136 = 0.082$$

$$10) \text{ UNIT DURATION, } D \leq t_L / 3 = \frac{0.082}{3} = 0.027 < 0.083 \text{ hr.}$$

$$\text{USE } D = 0.035 \text{ hr}$$

$$11) \text{ TIME TO PEAK, } T_p = D/2 + t_L = \frac{0.035}{2} + 0.082 = 0.123 \text{ hr}$$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = \frac{484 \times 0.145}{0.123} = 570 \text{ cfs}$$

THE ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 3

DAM NAME: BENSON LAKE DAM # 30667

JOB NO. 1263

PROBABLE MAXIMUM PRECIPITATION

BY FR DATE 1/14/12

DETERMINATION OF PMP

1) Determine drainage area of the basin

D.A. = 92.5 A4

2) Determine PMP Index Rainfall (for D.A. = 200 sq. mi. & 24 hr. duration)

Location of centroid of basin,

Long. = 91° 28' 19"


Lat. = 38° 38' 35"

PMP = 25.2 (from Fig. 1, HMR 33)

Zone = 7

3) Determine basin rainfall in terms of percentage of PMP Index
Rainfall for various durations.
(from Fig. 2, HMR 33)

Duration (Hrs.)	Percent of Index Rainfall (%)	Total Rainfall (Inches)	Rainfall Increments (Inches)	Duration of Increment (Hrs.)
6	100	25.2	25.2	6
12	140	30.2	5	6
24	150	32.8	2.6	12



● LOCATION OF CENTROID OF BASIN

BENSON LAKE DAM
DETERMINATION OF PMP

383











FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONS
Percentage to be applied to 200 square miles
24 hour probable maximum precipitation 10.45
for the all season envelope



PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI - 1980 SHEET NO. 1 OF 1

DAM NAME: PEASON LAKE DAM # 30667 JOB NO. 1263

CURVE NUMBER DETERMINATION AT UPSTREAM PEASON LAKE DAM BY DATE

I) SOIL GROUP

WATERSHED SOILS IN THE BASIN CONSIST OF GROUP

A.
B.
C.
D.

GROUP B SOILS SEEM TO PREDOMINATE THE BASIN. THEREFORE,
ASSUME GROUP B SOILS FOR THE ENTIRE WATERSHED
FOR HYDROLOGIC PURPOSES.

II) COVER COMPLEX

ASSUMED
LAND USE

ASSUMED
HYDROLOGIC
CONDITION

PER CENT
AREA

CN
(AMC II)

FOREST

FAIR

70%

60

RANGE

FAIR

30%

69

III) CURVE NUMBER

WEIGHTED AVERAGE CN = 63 FOR AMC II

CURVE NUMBER = 80 FOR AMC III

PRC ENGINEERING CONSULTANTS, INC.


DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 1

REVISION NO. 1/11

JOB NO. 1263

DETERMINATION OF EFFECTIVE TOP OF DAM BY MAS DATE 6-9-80



Assuming a 5 ft/sec permissible velocity (Kentucky Blue Gravel-Sandy Silt) the effective top of dam is found to be 710.2 ft above U.S.L., which is higher than minimum top of dam elevation. Use the minimum top of dam elev. for overtopping analysis.

HEC1DB INPUT DATA

.....
 FLOOD HYDROGRAPH PACKAGE (MCH-1)
 DAM SAFETY VERIFICATION JULY 1978
 LAST MODIFICATION: 76 80 1 7

1	41	DAM SAFETY INSPECTION - MISSOURI									
2	42	HENSON LAKE DAM (NO 30657)									
3	43	D/F AND HALF D/F WITH U/S DAM BREAK IN CASE OF DAM OVERTOP									
4	44	300	0	0	0	0	0	0	0	0	0
5	45	1	1	2	1						
6	46	1	1	2	1						
7	47	1	1	2	1						
8	48	1	1	2	1						
9	49	1	1	2	1						
10	50	1	1	2	1						
11	51	1	1	2	1						
12	52	1	1	2	1						
13	53	1	1	2	1						
14	54	1	1	2	1						
15	55	1	1	2	1						
16	56	1	1	2	1						
17	57	1	1	2	1						
18	58	1	1	2	1						
19	59	1	1	2	1						
20	60	1	1	2	1						
21	61	1	1	2	1						
22	62	1	1	2	1						
23	63	1	1	2	1						
24	64	1	1	2	1						
25	65	1	1	2	1						
26	66	1	1	2	1						
27	67	1	1	2	1						
28	68	1	1	2	1						
29	69	1	1	2	1						
30	70	1	1	2	1						
31	71	1	1	2	1						
32	72	1	1	2	1						
33	73	1	1	2	1						
34	74	1	1	2	1						
35	75	1	1	2	1						
36	76	1	1	2	1						
37	77	1	1	2	1						
38	78	1	1	2	1						
39	79	1	1	2	1						
40	80	1	1	2	1						
41	81	1	1	2	1						
42	82	1	1	2	1						
43	83	1	1	2	1						
44	84	1	1	2	1						
45	85	1	1	2	1						
46	86	1	1	2	1						
47	87	1	1	2	1						
48	88	1	1	2	1						
49	89	1	1	2	1						
50	90	1	1	2	1						
51	91	1	1	2	1						
52	92	1	1	2	1						
53	93	1	1	2	1						
54	94	1	1	2	1						
55	95	1	1	2	1						
56	96	1	1	2	1						
57	97	1	1	2	1						
58	98	1	1	2	1						
59	99	1	1	2	1						
60	100	1	1	2	1						
61	101	1	1	2	1						
62	102	1	1	2	1						
63	103	1	1	2	1						
64	104	1	1	2	1						
65	105	1	1	2	1						
66	106	1	1	2	1						
67	107	1	1	2	1						
68	108	1	1	2	1						
69	109	1	1	2	1						
70	110	1	1	2	1						
71	111	1	1	2	1						
72	112	1	1	2	1						
73	113	1	1	2	1						
74	114	1	1	2	1						
75	115	1	1	2	1						
76	116	1	1	2	1						
77	117	1	1	2	1						
78	118	1	1	2	1						
79	119	1	1	2	1						
80	120	1	1	2	1						
81	121	1	1	2	1						
82	122	1	1	2	1						
83	123	1	1	2	1						
84	124	1	1	2	1						
85	125	1	1	2	1						
86	126	1	1	2	1						
87	127	1	1	2	1						
88	128	1	1	2	1						
89	129	1	1	2	1						
90	130	1	1	2	1						
91	131	1	1	2	1						
92	132	1	1	2	1						
93	133	1	1	2	1						
94	134	1	1	2	1						
95	135	1	1	2	1						
96	136	1	1	2	1						
97	137	1	1	2	1						
98	138	1	1	2	1						
99	139	1	1	2	1						
100	140	1	1	2	1						

LINE	DESCRIPTION	734	1	742	745	1
1	10/5 - 1/5					
2	CHANNEL ROUTING		1			
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						
61						
62						
63						
64						
65						
66						
67						
68						
69						
70						
71						
72						
73						
74						
75						
76						
77						
78						
79						
80						
81						
82						
83						
84						
85						
86						
87						
88						
89						
90						
91						
92						
93						
94						
95						
96						
97						
98						
99						
100						

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS

.....

• • • • •

RJA
DATE 2/26/05
TIME 11:06 AM

IN SAFETY INSPECTION - MISSOURI
 - FASCO, LAW FOR TWO YEARS
 ONE AND HALF YEARS WITH U.S. BANK IN CASE OF BANK CRASH/OUT

[illegible]

1 = 01157 C = 01154 I = 4770'
C = 03530 I = 01157 I = 01157

CC-01-116

.....

.....

.....

.....

.....

SUB-AREA RUNOFF COMPUTATION

RUNOFF CALCULATIONS FOR U/S DAM DRAINAGE AREA

ISYAG	ICOMP	IFCON	IFRFR	IMPLY	IMM	ISTAGE	IAUTC
0	0	0	0	0	1	0	0

	HYDROGRAPHIC DATA	RATIO	ISOM	ISAVE	LOCAL
	YAREA	SUMP	TRSDA	TRSPC	
IMVCS	.09	0.60	.00	1.00	
IUMG	2				

PRECIP DATA			
SPOT	PMS	R6	R12
0.00	25.00	100.00	120.00
0.00			130.00
			0.00
			R48
			R72
			P96
			0.00

LOSS DATA										
LEADPT	SPRBN	DLTAR	RTIOL	FRATL	STRES	RTION	STATL	INSTL	ALSPX	RTIND
0	3.00	0.00	1.00	0.00	0.00	1.00	-1.00	-40.00	0.00	0.00

CURVE VC = -60.00 WITNESS = -1.00 EFFECT CN = 80.00

UNIT HYDROGRAPH DATA
TC= 3.00 LAG= .09

```
SVR1QZ 0.00 RECESSION DATA QRCNV= 0.0
```

TIME INCREMENT TOO LARGE--(NWD IS GT LAG/2)

UNIT-TO-CORRESPOND / END OF PERIOD ORIGINATES, YC= 0.00 HOURS, LAG= 0.00, VOL= 1.000

[illegible]

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL
CFS	1.98	22.5	68.	66.	196.7
CMS	33.	16.	2.	2.	58.8
INCHES		61.50	29.94	29.94	29.94
MM		260.47	760.47	760.47	760.47
AC-F		11.	136.	136.	136.
CU M		137.	137.	167.	167.

HYDROGRAPH AT STA/S DAM FOR PLAN 1, RTIO 1


[illegible]

PEAK OUTFLOW IS 1091. AT TIME 15.67 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	1091.	251.	78.	67.	1005.	569.
CMS	31.	7.	2.	2.	569.	3056.
INCHES		25.27	76.56	50.56	277.22	776.22
MM		641.86	1766.22	776.22	138.	138.
AC-FT		114.	138.	138.	171.	171.
THOUS CU M		141.	171.	171.	171.	171.

THE LEAK BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .0121 HOURS DURING BREACH FORMATION. DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .005 HOURS. THIS TABLE PRESENTS THE HYDROGRAPH FOR DOWNSTREAM CALCULATION WITH THE COMPUTED BREACH HYDROGRAPH. INTERPOLATED VALUES ARE INDICATED FROM END-OF-PERIOD VALUES.

TIME (HOURS)	TIME OF BREACH (HOURS)	INTERPOLATED HYDROGRAPH (CFS)	COMPUTED HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (AC-FT)
13.432	1.000	152	152	0	0	0
13.444	1.012	154	154	0	0	0
13.456	1.024	156	156	0	0	0
13.468	1.036	158	158	0	0	0
13.480	1.048	160	160	0	0	0
13.492	1.060	162	162	0	0	0
13.504	1.072	164	164	0	0	0
13.516	1.084	166	166	0	0	0
13.528	1.096	168	168	0	0	0
13.540	1.108	170	170	0	0	0
13.552	1.120	172	172	0	0	0
13.564	1.132	174	174	0	0	0
13.576	1.144	176	176	0	0	0
13.588	1.156	178	178	0	0	0
13.600	1.168	180	180	0	0	0
13.612	1.180	182	182	0	0	0
13.624	1.192	184	184	0	0	0
13.636	1.204	186	186	0	0	0
13.648	1.216	188	188	0	0	0
13.660	1.228	190	190	0	0	0
13.672	1.240	192	192	0	0	0
13.684	1.252	194	194	0	0	0
13.696	1.264	196	196	0	0	0
13.708	1.276	198	198	0	0	0
13.720	1.288	200	200	0	0	0
13.732	1.300	202	202	0	0	0
13.744	1.312	204	204	0	0	0
13.756	1.324	206	206	0	0	0
13.768	1.336	208	208	0	0	0
13.780	1.348	210	210	0	0	0
13.792	1.360	212	212	0	0	0
13.804	1.372	214	214	0	0	0
13.816	1.384	216	216	0	0	0
13.828	1.396	218	218	0	0	0
13.840	1.408	220	220	0	0	0
13.852	1.420	222	222	0	0	0
13.864	1.432	224	224	0	0	0
13.876	1.444	226	226	0	0	0
13.888	1.456	228	228	0	0	0
13.900	1.468	230	230	0	0	0
13.912	1.480	232	232	0	0	0
13.924	1.492	234	234	0	0	0
13.936	1.504	236	236	0	0	0
13.948	1.516	238	238	0	0	0
13.960	1.528	240	240	0	0	0
13.972	1.540	242	242	0	0	0
13.984	1.552	244	244	0	0	0
13.996	1.564	246	246	0	0	0
14.008	1.576	248	248	0	0	0
14.020	1.588	250	250	0	0	0
14.032	1.600	252	252	0	0	0
14.044	1.612	254	254	0	0	0
14.056	1.624	256	256	0	0	0
14.068	1.636	258	258	0	0	0
14.080	1.648	260	260	0	0	0
14.092	1.660	262	262	0	0	0
14.104	1.672	264	264	0	0	0
14.116	1.684	266	266	0	0	0
14.128	1.696	268	268	0	0	0
14.140	1.708	270	270	0	0	0
14.152	1.720	272	272	0	0	0
14.164	1.732	274	274	0	0	0
14.176	1.744	276	276	0	0	0
14.188	1.756	278	278	0	0	0
14.200	1.768	280	280	0	0	0
14.212	1.780	282	282	0	0	0
14.224	1.792	284	284	0	0	0
14.236	1.804	286	286	0	0	0
14.248	1.816	288	288	0	0	0
14.260	1.828	290	290	0	0	0
14.272	1.840	292	292	0	0	0
14.284	1.852	294	294	0	0	0
14.296	1.864	296	296	0	0	0
14.308	1.876	298	298	0	0	0
14.320	1.888	300	300	0	0	0
14.332	1.900	302	302	0	0	0
14.344	1.912	304	304	0	0	0
14.356	1.924	306	306	0	0	0
14.368	1.936	308	308	0	0	0
14.380	1.948	310	310	0	0	0
14.392	1.960	312	312	0	0	0
14.404	1.972	314	314	0	0	0
14.416	1.984	316	316	0	0	0
14.428	1.996	318	318	0	0	0
14.440	2.008	320	320	0	0	0
14.452	2.020	322	322	0	0	0
14.464	2.032	324	324	0	0	0
14.476	2.044	326	326	0	0	0
14.488	2.056	328	328	0	0	0
14.500	2.068	330	330	0	0	0
14.512	2.080	332	332	0	0	0
14.524	2.092	334	334	0	0	0
14.536	2.104	336	336	0	0	0
14.548	2.116	338	338	0	0	0
14.560	2.128	340	340	0	0	0
14.572	2.140	342	342	0	0	0
14.584	2.152	344	344	0	0	0
14.596	2.164	346	346	0	0	0
14.608	2.176	348	348	0	0	0
14.620	2.188	350	350	0	0	0
14.632	2.200	352	352	0	0	0
14.644	2.212	354	354	0	0	0
14.656	2.224	356	356	0	0	0
14.668	2.236	358	358	0	0	0
14.680	2.248	360	360	0	0	0
14.692	2.260	362	362	0	0	0
14.704	2.272	364	364	0	0	0
14.716	2.284	366	366	0	0	0
14.728	2.296	368	368	0	0	0
14.740	2.308	370	370	0	0	0
14.752	2.320	372	372	0	0	0
14.764	2.332	374	374	0	0	0
14.776	2.344	376	376	0	0	0
14.788	2.356	378	378	0	0	0
14.800	2.368	380	380	0	0	0
14.812	2.380	382	382	0	0	0
14.824	2.392	384	384	0	0	0
14.836	2.404	386	386	0	0	0
14.848	2.416	388	388	0	0	0
14.860	2.428	390	390	0	0	0
14.872	2.440	392	392	0	0	0
14.884	2.452	394	394	0	0	0
14.896	2.464	396	396	0	0	0
14.908	2.476	398	398	0	0	0
14.920	2.488	400	400	0	0	0
14.932	2.500	402	402	0	0	0
14.944	2.512	404	404	0	0	0
14.956	2.524	406	406	0	0	0
14.968	2.536	408	408	0	0	0
14.980	2.548	410	410	0	0	0
14.992	2.560	412	412	0	0	0
15.004	2.572	414	414	0	0	0
15.016	2.584	416	416	0	0	0
15.028	2.596	418	418	0	0	0
15.040	2.608	420	420	0	0	0
15.052	2.620	422	422	0	0	0
15.064	2.632	424	424	0	0	0
15.076	2.644	426	426	0	0	0
15.088	2.656	428	428	0	0	0
15.100	2.668	430	430	0	0	0
15.112	2.680	432	432	0	0	0
15.124	2.692	434	434	0	0	0
15.136	2.704	436	436	0	0	0
15.148	2.716	438	438	0	0	0
15.160	2.728	440	440	0	0	0
15.172	2.740	442	442	0	0	0
15.184	2.752	444	444	0	0	0
15.196	2.764	446	446	0	0	0
15.208	2.776	448	448	0	0	0
15.220	2.788	450	450	0	0	0
15.232	2.800	452	452	0	0	0
15.244	2.812	454	454	0	0	0
15.256	2.824	456	456	0	0	0
15.268	2.836	458	458	0	0	0
15.280	2.848	460	460	0	0	0
15.292	2.860	462	462	0	0	0
15.304	2.872	464	464	0	0	0
15.316	2.884	466	466	0	0	0
15.328	2.896	468	468	0	0	0
15.340	2.908	470	470	0	0	0
15.352	2.920	472	472	0	0	0
15.364	2.932	474	474	0	0	0
15.376	2.944	476	476	0	0	0
15.388	2.956	478	478	0	0	0
15.400	2.968	480	480	0	0	0
15.412	2.980	482	482	0	0	0
15.424	2.992	484	484	0	0	0
15.436	3.004	486	486	0	0	0
15.448	3.016	488	488	0	0	0
15.460	3.028	490	490	0	0	0
15.472	3.040	492	492	0	0	0
15.484	3.052	494	494	0	0	0
15.496	3.064	496	496	0	0	0
15.508	3.076	498	498	0	0	0
15.520	3.088	500	500	0	0	0
15.532	3.100	502	502	0	0	0
15.544	3.112	504	504	0	0	0
15.556	3.124	506	506	0	0	0
15.568	3.136	508	508	0	0	0
15.580	3.148	510	510	0	0	0
15.592	3.160	512	512	0	0	0
15.604	3.172	514	514	0	0	0
15.616	3.184	516	516	0	0	0
15.628	3.196	518	518	0	0	0
15.640	3.208	520	520	0	0	0
15.652	3.220	522	522	0	0	0
15.664	3.232	524	524	0	0	0
15.676	3.244	526	526	0	0	0
15.688	3.256	528	528	0	0	0
15.700	3.268	530	530	0	0	0
15.712	3.280	532	532	0	0	0
15.724	3.292	534	534	0	0	0
15.736	3.304	536	536	0	0	0
15.748	3.316	538	538	0	0	0
15.760	3.328	540	540	0	0	0
15.772	3.340	542	542	0	0	0
15.784	3.352	544	544	0	0	0
15.796	3.364	546	546	0	0	0
15.808	3.376	548	548	0	0	0
15.820	3.388	550	550	0	0	0
15.832	3.400	552	552	0	0	0
15.844	3.412	554	554	0	0</	

STATISTICS 7A^u

SECRETARY OF THE ARMY

IN-0-P:WIC - CIVILIAN ORIGINATES

[illegible]

AD-A106 167


PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. BENSON LAKE DAM (MO 30667), MISSOU--ETC(U)
SEP 80 W G SHIFRIN
DACW43-80-C-0094

F/G 13/13

NL

UNCLASSIFIED

2 1/2 2




END
DATE
FILMED
11-8
DTIC

THE FOLLOWING HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .021 HOUR, USING BREACH FORMATION, COMPUTED CALCULATIONS AND USE A TIME INTERVAL OF .0013 HOUR. THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERPOLATE FLOODS ARE INTERPOLATED FROM ENDSERIES VALUES.

TIME (HOURS)	TIME FROM BEGINNING OF BREACH (HOURS)	INTERPOLATED BREACH HYDROGRAPH (CFS)	COMPUTED BREACH HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (CFS)
15.000	0.000	121	121	0	0
15.021	.021	141	230	11	11
15.042	.042	161	366	26	37
15.063	.063	181	481	42	79
15.084	.084	201	581	61	140
15.105	.105	221	666	85	225
15.126	.126	241	737	97	322
15.147	.147	261	797	136	458
15.168	.168	281	847	166	624
15.189	.189	301	887	186	810
15.210	.210	321	917	197	1007
15.231	.231	341	947	207	1214
15.252	.252	361	967	217	1431
15.273	.273	381	977	227	1658
15.294	.294	401	977	237	1895
15.315	.315	421	967	247	2142
15.336	.336	441	947	257	2399
15.357	.357	461	917	267	2666
15.378	.378	481	877	277	2943
15.399	.399	501	827	287	3230
15.420	.420	521	767	297	3527
15.441	.441	541	697	307	3834
15.462	.462	561	617	317	4151
15.483	.483	581	527	327	4478
15.504	.504	601	427	337	4815
15.525	.525	621	317	347	5162
15.546	.546	641	207	357	5519
15.567	.567	661	97	367	5886
15.588	.588	681	0	377	6263
15.609	.609	701	0	387	6650
15.630	.630	721	0	397	7047
15.651	.651	741	0	407	7454
15.672	.672	761	0	417	7871
15.693	.693	781	0	427	8298
15.714	.714	801	0	437	8735
15.735	.735	821	0	447	9182
15.756	.756	841	0	457	9639
15.777	.777	861	0	467	10106
15.798	.798	881	0	477	10583
15.819	.819	901	0	487	11070
15.840	.840	921	0	497	11567
15.861	.861	941	0	507	12074
15.882	.882	961	0	517	12591
15.903	.903	981	0	527	13118
15.924	.924	1001	0	537	13655
15.945	.945	1021	0	547	14202
15.966	.966	1041	0	557	14759
15.987	.987	1061	0	567	15326
16.008	1.008	1081	0	577	15903
16.029	1.029	1101	0	587	16490
16.050	1.050	1121	0	597	17087
16.071	1.071	1141	0	607	17694
16.092	1.092	1161	0	617	18311
16.113	1.113	1181	0	627	18938
16.134	1.134	1201	0	637	19575
16.155	1.155	1221	0	647	20222
16.176	1.176	1241	0	657	20879
16.197	1.197	1261	0	667	21546
16.218	1.218	1281	0	677	22223
16.239	1.239	1301	0	687	22910
16.260	1.260	1321	0	697	23607
16.281	1.281	1341	0	707	24314
16.302	1.302	1361	0	717	25031
16.323	1.323	1381	0	727	25758
16.344	1.344	1401	0	737	26495
16.365	1.365	1421	0	747	27242
16.386	1.386	1441	0	757	28000
16.407	1.407	1461	0	767	28767
16.428	1.428	1481	0	777	29544
16.449	1.449	1501	0	787	30331
16.470	1.470	1521	0	797	31128
16.491	1.491	1541	0	807	31935
16.512	1.512	1561	0	817	32752
16.533	1.533	1581	0	827	33579
16.554	1.554	1601	0	837	34416
16.575	1.575	1621	0	847	35263
16.596	1.596	1641	0	857	36120
16.617	1.617	1661	0	867	36987
16.638	1.638	1681	0	877	37864
16.659	1.659	1701	0	887	38751
16.680	1.680	1721	0	897	39648
16.701	1.701	1741	0	907	40555
16.722	1.722	1761	0	917	41472
16.743	1.743	1781	0	927	42399
16.764	1.764	1801	0	937	43336
16.785	1.785	1821	0	947	44283
16.806	1.806	1841	0	957	45240
16.827	1.827	1861	0	967	46207
16.848	1.848	1881	0	977	47184
16.869	1.869	1901	0	987	48171
16.890	1.890	1921	0	997	49168
16.911	1.911	1941	0	1007	50175
16.932	1.932	1961	0	1017	51192
16.953	1.953	1981	0	1027	52219
16.974	1.974	2001	0	1037	53256
16.995	1.995	2021	0	1047	54303
17.016	2.016	2041	0	1057	55360
17.037	2.037	2061	0	1067	56427
17.058	2.058	2081	0	1077	57504
17.079	2.079	2101	0	1087	58591
17.100	2.100	2121	0	1097	59688
17.121	2.121	2141	0	1107	60795
17.142	2.142	2161	0	1117	61912
17.163	2.163	2181	0	1127	63039
17.184	2.184	2201	0	1137	64176
17.205	2.205	2221	0	1147	65323
17.226	2.226	2241	0	1157	66480
17.247	2.247	2261	0	1167	67647
17.268	2.268	2281	0	1177	68824
17.289	2.289	2301	0	1187	70011
17.310	2.310	2321	0	1197	71208
17.331	2.331	2341	0	1207	72415
17.352	2.352	2361	0	1217	73632
17.373	2.373	2381	0	1227	74859
17.394	2.394	2401	0	1237	76096
17.415	2.415	2421	0	1247	77343
17.436	2.436	2441	0	1257	78600
17.457	2.457	2461	0	1267	79867
17.478	2.478	2481	0	1277	81144
17.499	2.499	2501	0	1287	82431
17.520	2.520	2521	0	1297	83728
17.541	2.541	2541	0	1307	85035
17.562	2.562	2561	0	1317	86352
17.583	2.583	2581	0	1327	87679
17.604	2.604	2601	0	1337	89016
17.625	2.625	2621	0	1347	90363
17.646	2.646	2641	0	1357	91720
17.667	2.667	2661	0	1367	93087
17.688	2.688	2681	0	1377	94464
17.709	2.709	2701	0	1387	95851
17.730	2.730	2721	0	1397	97248
17.751	2.751	2741	0	1407	98655
17.772	2.772	2761	0	1417	100072
17.793	2.793	2781	0	1427	101500
17.814	2.814	2801	0	1437	102937
17.835	2.835	2821	0	1447	104384
17.856	2.856	2841	0	1457	105841
17.877	2.877	2861	0	1467	107308
17.898	2.898	2881	0	1477	108785
17.919	2.919	2901	0	1487	110272
17.940	2.940	2921	0	1497	111769
17.961	2.961	2941	0	1507	113276
17.982	2.982	2961	0	1517	114793
18.003	3.003	2981	0	1527	116320
18.024	3.024	3001	0	1537	117857
18.045	3.045	3021	0	1547	119404
18.066	3.066	3041	0	1557	120961
18.087	3.087	3061	0	1567	122528
18.108	3.108	3081	0	1577	124105
18.129	3.129	3101	0	1587	125692
18.150	3.150	3121	0	1597	127289
18.171	3.171	3141	0	1607	128896
18.192	3.192	3161	0	1617	130513
18.213	3.213	3181	0	1627	132140
18.234	3.234	3201	0	1637	133777
18.255	3.255	3221	0	1647	135424
18.276	3.276	3241	0	1657	137081
18.297	3.297	3261	0	1667	138748
18.318	3.318	3281	0	1677	140425
18.339	3.339	3301	0	1687	142112
18.360	3.360	3321	0	1697	143809
18.381	3.381	3341	0	1707	145516
18.402	3.402	3361	0	1717	147233
18.423	3.423	3381	0	1727	148960
18.444	3.444	3401	0	1737	150697
18.465	3.465	3421	0	1747	152444
18.486	3.486	3441	0	1757	154201
18.507	3.507	3461	0	1767	155968
18.528	3.528	3481	0	1777	157745
18.549	3.549	3501	0	1787	159532
18.570	3.570	3521	0	1797	161329
18.591	3.591	3541	0	1807	163136
18.612	3.612	3561	0	1817	164953
18.633	3.633	3581	0	1827	166780
18.654	3.654	3601	0	1837	168617
18.675	3.675	3621	0	1847	170464
18.696	3.696	3641	0	1857	172321
18.717	3.717	3661	0	1867	174188
18.738	3.738	3681	0	1877	176065
18.759	3.759	3701	0	1887	177952
18.780	3.780	3721	0	1897	179859
18.801	3.801	3741	0	1907	181776
18.822	3.822	3761	0	1917	183703
18.843	3.843	3781	0	1927	185640
18.864	3.864	3801	0	1937	187587
18.885	3.885	3821	0	1947	189544
18.906	3.906	3841	0	1957	191511
18.927	3.927	3861	0	1967	193488
18.948	3.948	3881	0	1977	195475
18.969	3.969	3901	0	1987	197472
18.990	3.990	3921	0	1997	199479
19.011	4.011	3941	0	2007	201496
19.032	4.032	3961	0	2017	203523
19.053	4.053	3981	0	2027	205560
19.074	4.074	4001	0	2037	207607
19.095	4.095	4021	0	2047	209664
19.116	4.116	4041	0	2057	211731
19.137	4.137	4061	0	2067	213808
19.158	4.158	4081	0	2077	215895
19.179	4.179	4101	0	2087	217992
19.200	4.200	4121	0	2097	220099
19.221	4.221	4141	0	2107	222216
19.242	4.242	4161	0	2117	224343
19.263	4.263	4181	0	2127	226480
19.284	4.284	4201	0	2137	228627
1					

DATE

STATION/C NAME



TESTED -S/S	ICOMP	TCCO	TRAP	JPLY	JPRY	INAME	PAGE	AUTO
0	1	0	0	0	0	1	0	0
CLOS	0	HOW TO DATE						
0	0	FPS	ISAME	PORT	TEMP		LSTR	
0	0	1	1	0	0			
NSTPS	INSTL	987	00000000	X	0	00000000	ISPRAT	0

24(1)	GV(2)	GV(3)	CLAV	ELMAX	RLVY	SFL
0000	0000	0000	720	7420	1000	0000

CROSS	SECTION	COORDINATES--STA	ELEV	STA	ELEV--ETC
3.00	747.00	40.00	750.00	93.00	723.00
110.00	723.00	140.00	730.00	250.00	740.00

	0.00	.28	.65	1.01	1.88	3.08	4.72	6.79	9.30	12.25
STORAGE	15.62	19.28	23.22	27.44	31.95	36.73	41.79	47.13	52.75	58.65
ROUTING	0.60	53.46	180.55	385.70	749.57	1334.89	2191.01	3376.07	4982.69	6999.78
	9579.61	12758.61	16401.67	20544.81	25506.43	30385.85	35440.21	40850.35	46954.68	53482.15
STAGE	720.00	721.05	722.11	723.16	724.21	725.26	726.32	727.37	728.42	729.47
	730.53	731.58	732.63	733.68	734.74	735.79	736.84	737.89	738.93	740.00
FLOW	0.89	53.46	180.55	386.70	749.57	1324.89	2181.01	3376.07	4982.69	6999.72
	9829.61	12758.61	16401.67	20864.81	25506.43	30565.28	35440.21	40850.35	46954.68	537682.15

STATION S-D/S. PLAN 1. P.T. 1

[illegible]

[illegible][illegible]

	PEAK	5-10% -4-HOUR	72-HOUR	TOTAL VOLUME
CMS	1000	23	67	20105
CMS	29	7	2	569
INCHES		25.6	33.56	30.7
M	61.52	776.10	776.10	776.10
10-FT	11	130	130	130
10-FT	141	171	171	171

MAXIMUM STORAGE = 20

MAXIMUM STAGE IS 780.7

STATION S-O/S, PLAN 1, RTIC 2

[illegible]

	PEAK	6-HOUR	12-HOUR	TOTAL
CFS	539	118	36	1053
CFS	15	9	1	290
1-CHL		12.95	15.5	15.56
1-CHL		23.80	395.11	395.11
1-CHL		55	70	70
1-CHL		70	87	87
THOUS. CU		73		

MAXIMUM STORAGE = 10

MAXIMUM STAGE IS 723.6

.....

.....

.....

.....

.....

SUB-AREA RUNOFF COMPUTATION

RUNOFF CALCULATION FOR RENSON LAKE DAM RUNOFF AREA

ISTAG	IComp	IECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
30667	0	0	0	0	0	1	0	0

HYDROGRAPH DATA		RATIO		ISNOW - ISWE		LOCAL	
ISWDC	ISNG	SNAP	TRSDA	TRSPC	ISNOW	ISWE	LOCAL
1	2	0.00	.15	1.00	0	1	0
		.15					

PRECIP DATA

SPFE	PHS	R5	R12	R24	R48	R96
0.00	29.20	100.00	120.00	130.00	0.00	0.00

LOSS DATA

LOCAL DATA										
LABOPT	STAKA	OLYKA	RTIOL	FRAIN	STKRS	RTIOK	STRTL	CNSTL	ALGMY	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-00.00	-1.00	0.00

REPAIR NO = 00.00 WEIGHTS = -1.00 EFFECT CN = 00.00

UNIT HYDROGRAPH DATA

VC# 0-00 LAG# 00

STRIKE 3.37 RECUSSION DATA RTIME 1.00
GREYNE 1.00

TIME INC (UNT) TO LARGE--(CNG IS ST 146/7)

RAIT HYPER KAP 7 END OF PERIOD OPTICALS ICE 5. 9.00 HOURS LA 2. 0.0R VOLE 1.00
433. 102. 52. 17.

HR.DA	HR.DV	PERIOD	RAIN	EXCS	LOSS	ENG-OF-PERIOD	HR.DA	HR.DV	PERIOD	RAIN	EXCS	LOSS	COMP Q
1.01	0.05	1	.31	0.00	.01	0.	1.01	12.35	151	.21	.20	.01	218.
1.01	0.10	2	.01	0.00	.01	0.	1.01	12.40	152	.21	.20	.01	219.
1.01	0.15	3	.01	0.00	.01	0.	1.01	12.45	153	.21	.20	.01	220.
1.01	0.20	4	.01	0.00	.01	0.	1.01	12.50	154	.21	.20	.01	221.
1.01	0.25	5	.01	0.00	.01	0.	1.01	12.55	155	.21	.20	.01	222.
1.01	0.30	6	.01	0.00	.01	0.	1.01	13.00	156	.21	.20	.01	223.
1.01	0.35	7	.01	0.00	.01	0.	1.01	13.05	157	.21	.20	.01	224.
1.01	0.40	8	.01	0.00	.01	0.	1.01	13.10	158	.21	.20	.01	225.
1.01	0.45	9	.01	0.00	.01	0.	1.01	13.15	159	.21	.20	.01	226.
1.01	0.50	10	.01	0.00	.01	0.	1.01	13.20	160	.21	.20	.01	227.
1.01	0.55	11	.01	0.00	.01	0.	1.01	13.25	161	.21	.20	.01	228.
1.01	1.00	12	.01	0.00	.01	0.	1.01	13.30	162	.21	.20	.01	229.
1.01	1.05	13	.01	0.00	.01	0.	1.01	13.35	163	.21	.20	.01	230.
1.01	1.10	14	.01	0.00	.01	0.	1.01	13.40	164	.21	.20	.01	231.
1.01	1.15	15	.01	0.00	.01	0.	1.01	13.45	165	.21	.20	.01	232.
1.01	1.20	16	.01	0.00	.01	0.	1.01	13.50	166	.21	.20	.01	233.
1.01	1.25	17	.01	0.00	.01	0.	1.01	13.55	167	.21	.20	.01	234.
1.01	1.30	18	.01	0.00	.01	0.	1.01	14.00	168	.21	.20	.01	235.
1.01	1.35	19	.01	0.00	.01	0.	1.01	14.05	169	.21	.20	.01	236.
1.01	1.40	20	.01	0.00	.01	0.	1.01	14.10	170	.21	.20	.01	237.
1.01	1.45	21	.01	0.00	.01	0.	1.01	14.15	171	.21	.20	.01	238.
1.01	1.50	22	.01	0.00	.01	0.	1.01	14.20	172	.21	.20	.01	239.
1.01	1.55	23	.01	0.00	.01	0.	1.01	14.25	173	.21	.20	.01	240.
1.01	2.00	24	.01	0.00	.01	0.	1.01	14.30	174	.21	.20	.01	241.
1.01	2.05	25	.01	0.00	.01	0.	1.01	14.35	175	.21	.20	.01	242.
1.01	2.10	26	.01	0.00	.01	0.	1.01	14.40	176	.21	.20	.01	243.
1.01	2.15	27	.01	0.00	.01	0.	1.01	14.45	177	.21	.20	.01	244.
1.01	2.20	28	.01	0.00	.01	0.	1.01	14.50	178	.21	.20	.01	245.
1.01	2.25	29	.01	0.00	.01	0.	1.01	14.55	179	.21	.20	.01	246.
1.01	2.30	30	.01	0.00	.01	0.	1.01	15.00	180	.21	.20	.01	247.
1.01	2.35	31	.01	0.00	.01	0.	1.01	15.05	181	.21	.20	.01	248.
1.01	2.40	32	.01	0.00	.01	0.	1.01	15.10	182	.21	.20	.01	249.
1.01	2.45	33	.01	0.00	.01	0.	1.01	15.15	183	.21	.20	.01	250.
1.01	2.50	34	.01	0.00	.01	0.	1.01	15.20	184	.21	.20	.01	251.
1.01	2.55	35	.01	0.00	.01	0.	1.01	15.25	185	.21	.20	.01	252.
1.01	3.00	36	.01	0.00	.01	0.	1.01	15.30	186	.21	.20	.01	253.
1.01	3.05	37	.01	0.00	.01	0.	1.01	15.35	187	.21	.20	.01	254.
1.01	3.10	38	.01	0.00	.01	0.	1.01	15.40	188	.21	.20	.01	255.
1.01	3.15	39	.01	0.00	.01	0.	1.01	15.45	189	.21	.20	.01	256.
1.01	3.20	40	.01	0.00	.01	0.	1.01	15.50	190	.21	.20	.01	257.
1.01	3.25	41	.01	0.00	.01	0.	1.01	15.55	191	.21	.20	.01	258.
1.01	3.30	42	.01	0.00	.01	0.	1.01	16.00	192	.21	.20	.01	259.
1.01	3.35	43	.01	0.00	.01	0.	1.01	16.05	193	.21	.20	.01	260.
1.01	3.40	44	.01	0.00	.01	0.	1.01	16.10	194	.21	.20	.01	261.
1.01	3.45	45	.01	0.00	.01	0.	1.01	16.15	195	.21	.20	.01	262.
1.01	3.50	46	.01	0.00	.01	0.	1.01	16.20	196	.21	.20	.01	263.
1.01	3.55	47	.01	0.00	.01	0.	1.01	16.25	197	.21	.20	.01	264.
1.01	4.00	48	.01	0.00	.01	0.	1.01	16.30	198	.21	.20	.01	265.
1.01	4.05	49	.01	0.00	.01	0.	1.01	16.35	199	.21	.20	.01	266.

1.01	4.10	5.9	7.1	7.9	7.1	2.	1.01	16.43	230	.29	.29	.00	327.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	231	.29	.29	.00	328.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	232	.29	.29	.00	329.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	233	.29	.29	.00	330.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	234	.29	.29	.00	331.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	235	.29	.29	.00	332.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	236	.29	.29	.00	333.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	237	.29	.29	.00	334.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	238	.29	.29	.00	335.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	239	.29	.29	.00	340.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	240	.29	.29	.00	341.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	241	.29	.29	.00	342.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	242	.29	.29	.00	343.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	243	.29	.29	.00	344.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	244	.29	.29	.00	345.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	245	.29	.29	.00	346.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	246	.29	.29	.00	347.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	247	.29	.29	.00	348.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	248	.29	.29	.00	349.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	249	.29	.29	.00	350.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	250	.29	.29	.00	351.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	251	.29	.29	.00	352.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	252	.29	.29	.00	353.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	253	.29	.29	.00	354.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	254	.29	.29	.00	355.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	255	.29	.29	.00	356.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	256	.29	.29	.00	357.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	257	.29	.29	.00	358.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	258	.29	.29	.00	359.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	259	.29	.29	.00	360.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	260	.29	.29	.00	361.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	261	.29	.29	.00	362.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	262	.29	.29	.00	363.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	263	.29	.29	.00	364.
1.01	4.10	5.1	7.1	7.9	7.1	2.	1.01	16.45	264	.29	.29	.00	365.</

1.01	5.10	110	.07	.70	.01	61.	1.01	21.90	263	.02	.02	.00	23.
1.01	5.15	111	.07	.70	.01	63.	1.01	21.95	261	.02	.02	.00	23.
1.01	5.20	112	.07	.70	.01	63.	1.01	21.95	263	.02	.02	.00	23.
1.01	5.25	113	.07	.70	.01	64.	1.01	21.95	263	.02	.02	.00	23.
1.01	5.30	114	.07	.70	.01	64.	1.01	21.95	264	.02	.02	.00	23.
1.01	5.35	115	.07	.70	.01	65.	1.01	21.95	265	.02	.02	.00	23.
1.01	5.40	116	.07	.70	.01	65.	1.01	21.95	265	.02	.02	.00	23.
1.01	5.45	117	.07	.70	.01	65.	1.01	21.95	267	.02	.02	.00	23.
1.01	5.50	118	.07	.70	.01	65.	1.01	21.95	267	.02	.02	.00	23.
1.01	5.55	119	.07	.70	.01	65.	1.01	21.95	268	.02	.02	.00	23.
1.01	5.60	120	.07	.70	.01	65.	1.01	21.95	268	.02	.02	.00	23.
1.01	5.65	121	.07	.70	.01	65.	1.01	21.95	270	.02	.02	.00	23.
1.01	5.70	122	.07	.70	.01	65.	1.01	21.95	271	.02	.02	.00	23.
1.01	5.75	123	.07	.70	.01	65.	1.01	21.95	272	.02	.02	.00	23.
1.01	5.80	124	.07	.70	.01	67.	1.01	21.95	273	.02	.02	.00	23.
1.01	5.85	125	.07	.70	.01	67.	1.01	21.95	274	.02	.02	.00	23.
1.01	5.90	126	.07	.70	.01	67.	1.01	21.95	274	.02	.02	.00	23.
1.01	5.95	127	.07	.70	.01	68.	1.01	21.95	275	.02	.02	.00	23.
1.01	6.00	128	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.05	129	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.10	130	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.15	131	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.20	132	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.25	133	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.30	134	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.35	135	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.40	136	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.45	137	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.50	138	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.55	139	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.60	140	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.65	141	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.70	142	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.75	143	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.80	144	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.85	145	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.90	146	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	6.95	147	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	7.00	148	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	7.05	149	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.
1.01	7.10	150	.07	.70	.01	68.	1.01	21.95	277	.02	.02	.00	23.

SUM 32.76 29.94 2.82 33576.
(832.31 760.11 72.11 950.77)

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
2026.	382.	117.	112.	33501.
57.	11.	7.	3.	951.
	24.48	29.94	29.94	28.84
	621.872	760.41	760.47	760.47
	199.	231.	231.	231.
	235.	285.	285.	285.

HYDROGRAPH AT STA 3667 FOR PLAN 1, RTIO 1

0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.

43
B-52

	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357
--	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------

PMF AND ONE-HALF PMF ROUTING

RECEIVED TELETYPE UNIT - AUG 1961

ISTG	ICD9	PCON	TYPE	JPLY	JPRI	INAME	ISTAGE	IAUTO
1	1	Q	2	Q	Q	1	Q	2
3467								

CLASS	CLOS	AVG	IRIS	ISAME	ROUTING UNIT
0.0	0.050	0.00	1	1	

STISN I C
TULSA, OKLA
LAWYER JAMES H. MCKINLEY

[illegible]

SURFACE AREA =

CAPACITANCE

ELEVATION =

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

10

10

01

!

1

1

...

•

YCP: L	DAY - 47A	DAVID
Y1: 0.0	COTD	EXPD
	3.00	0.00
		J.

TAFION 30667, FLAM 1, RAYIC 1

END-OF-PERIOD HYDROGRAPH ORDINATES

MC7J1NC

[illegible]

PEAK JUTF-0-15 2457. AT 1142 12067 H2043

STATION 30667, PLAN 1, RAT 22

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

STORAGE

DEAD CUTOFF IS 1346. AT TIME 14.75 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	1340	305	34	94	2787	2787
CvS	34	3	3	3	165	165
P-CFS		12	15	15	151	151
40		13	185	185	385	385
AC-F		151	185	185	516	516
THOUS CU M		1	230	230	461	461

PEAK FLOW AND STORAGE (CUMULATIVE) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUMULATIVE FEET PER SECOND, CUBIC METERS PER SECOND
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	RATIOS APPLIED TO FLOWS		
			PLAN	RATIO 1	RATIO 2
				1.00	1.00
HYDROGRAPH AT /S DAM	(.20	1	1159.	574.
			(32.60	16.41
ROUTED TO /S DAM	(.09	1	1091.	574.
			(3.90	16.33
ROUTED TO S-2/S	(.05	1	1204.	533.
			(23.44	15.24
HYDROGRAPH AT S-2/S	(.15	1	3026.	1011.
			(57.37	28.61
2 COMBINED	30667	.22	1	2945.	1519.
			(43.23	43.02
ROUTED TO	31667	.23	1	2687.	1340.
			(81.71	37.93

B-53
62

SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

54
B-68

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION: STORAGE OUTFLOW	INITIAL VALUE 742.00 0.0 0.0	SPILLWAY CREST 742.00 0.0 0.0	TOP OF DAM 745.00 0.0 148.0	MAXIMUM DEPTH OVER DAM 0.0 0.0 0.0	MAXIMUM STORAGE 10.0 10.0 10.0	MAXIMUM OUTFLOW CFS 100.0 100.0 100.0	DURATION OVER THE HOURS 0.5 0.5 0.5	TIME OF MAX OUTFLOW HOURS 15.67 15.67 15.67	TIME OF FATIGUE HOURS 15.62 15.62 15.62

PLAN 1 STATION 5 +0/S

RATIO	MAXIMUM FLOW/CF	MAXIMUM STAGE/FT	TIME HOURS
1.00	100.0	7.07	15.75
0.50	50.0	7.23.6	15.67

B-64

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION		INITIAL VALUE		FILLWAY CREST		TOP OF DAM	
	STORAGE	OUTFLOW	704.20	104.20	17.00	71.00	20.00	33.00
ALTD	MAXIMUM		MAXIMUM		MAXIMUM		TIME OF	
	RESERVOIR	STORAGE	DEPTH	OUTFLOW	OVER TOP	OF	DAY	FAILURE
PHF	WATER	FEET	FEET	CFS	FEET	HOURS	HOURS	HOURS
1.00	712.33	21.0	2.33	2487.0	5.25	15.67	0.00	0.00
0.50	711.37	2.0	1.0	1300.0	1.17	15.75	0.00	0.00

B-56

C

PERCENT OF PMF FLOOD ROUTING
EQUAL TO SPILLWAY CAPACITY

C

⁵⁷
B-66

[illegible]

B-58

26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49

B-68⁵⁹

Y9	10	.5	738	1	742	745	1
Y10	10/S -2/S						
Y11	CHANNEL ROUTING			1			
Y12	1						
Y13	.05	.05		720	740	1000	.025
Y14		740		730	90	723	95
Y15	110	723	190	730	250	740	
Y16	0	30667					1
Y17	1	2	.145		.145	1	
Y18	1	25.0	170	120	130		
Y19	1	.182					-1
Y20	0	0	1				
Y21	2	30667					1
Y22	1	30667					1
Y23	1	ROUTE HYDROGRAPH THROUGH BENSON LAKE DAM		1			
Y24	1	700.2	710.5	711.17	712	712.57	-700.2
Y25	0	233	500	1100	2200	3370	714.16
Y26	0	0	3	4	5	11	7932
Y27	0	0	700.2	700.5	712	720	17
Y28	0	0					733
Y29	0	0					
Y30	0	0					
Y31	0	0					
Y32	0	0					
Y33	0	0					
Y34	0	0					
Y35	0	0					
Y36	0	0					
Y37	0	0					
Y38	0	0					
Y39	0	0					
Y40	0	0					
Y41	0	0					
Y42	0	0					
Y43	0	0					
Y44	0	0					
Y45	0	0					
Y46	0	0					
Y47	0	0					
Y48	0	0					
Y49	0	0					
Y50	0	0					
Y51	0	0					
Y52	0	0					
Y53	0	0					
Y54	0	0					
Y55	0	0					
Y56	0	0					
Y57	0	0					
Y58	0	0					
Y59	0	0					
Y60	0	0					
Y61	0	0					
Y62	0	0					
Y63	0	0					
Y64	0	0					
Y65	0	0					
Y66	0	0					
Y67	0	0					
Y68	0	0					
Y69	0	0					
Y70	0	0					
Y71	0	0					
Y72	0	0					
Y73	0	0					
Y74	0	0					
Y75	0	0					
Y76	0	0					
Y77	0	0					
Y78	0	0					
Y79	0	0					
Y80	0	0					
Y81	0	0					
Y82	0	0					
Y83	0	0					
Y84	0	0					
Y85	0	0					
Y86	0	0					
Y87	0	0					
Y88	0	0					
Y89	0	0					
Y90	0	0					
Y91	0	0					
Y92	0	0					
Y93	0	0					
Y94	0	0					
Y95	0	0					
Y96	0	0					
Y97	0	0					
Y98	0	0					
Y99	0	0					
Y100	0	0					

51 710
52 89

51 710
52 89

REVIEW OF USE OF NETWORK CALCULATIONS

ROUTE HYDROGRAPH BY FS DAN
ROUTE HYDROGRAPH TO FS DAN
ROUTE HYDROGRAPH TO S-17
ROUTE HYDROGRAPH AT 3067
ROUTE HYDROGRAPH AT 3067
ROUTE HYDROGRAPH TO 3067
END OF NETWORK

60
B-65

CAPACITIVE	0.	1.	14.	18.	30.	92.	231.	425.
ELEVATIONS	695.	700.	708.	710.	717.	720.	730.	740.
	CHL	SPWD	CDW	EAU	FLVL	COI	CAREA	EAPL
	70.42	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DATA
TUFEL 710.0
COWD 0.0
FIXED 0.0
HAMID 0.

PEAK OUTFLOW IS 241. AT TIME 15.03 HOURS

PEAK OUTFLOW IS 303. AT TIME 15.03 HOURS

PEAK OUTFLOW IS 340. AT TIME 15.75 HOURS

PEAK OUTFLOW IS 399. AT TIME 15.75 HOURS

B-55

PLAN FL 2 AND STAGE 1 (END OF PERT) DATA FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQ. ARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS			
					1	2	3	4
					.16	.17	.18	.20
HYDROGRAPH AT /S DAM	1	.09	1	174.	127.	127.	209.	212.
ROUTED TO	1	.09	1	124.	127.	127.	127.	157.
ROUTED TO	1	.09	1	103.	124.	124.	124.	157.
HYDROGRAPH AT	1	.15	1	104.	124.	124.	124.	157.
2 COMBINED	1	.23	1	104.	124.	124.	124.	157.
ROUTED TO	1	.23	1	104.	124.	124.	124.	157.

B-58

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
	STORAGE	OUTFLOW	742.00	4.	742.00	4.	745.00	8.
			0.		0.		148.	
RATIO OF PHF	MAXIMUM RESERVOIR		MAXIMUM STORAGE		MAXIMUM OUTFLOW		DURATION OVER TOP	
	W.S.ELEV		AC-FT		CFS		HOURS	TIME OF MAX OUTFLOW HOURS
.15	744.59		7.		104.		0.00	15.75
.17	744.81		4.		127.		0.00	15.75
.18	744.90		3.		137.		0.00	15.75
.20	745.07		3.		150.		.15	15.79
								0.00
								0.00
								0.00
								15.75

PLAN 1 STATION S -D/S

RATIO	MAXIMUM		MAXIMUM		TIME	
	FLOW-CFS	STAGE-FT	STAGE-FT		HOURS	
.15	104.	721.5	721.5		15.83	
.17	127.	721.6	721.6		15.83	
.18	137.	721.7	721.7		15.83	
.20	150.	721.9	721.9		15.83	

B-52

PLAN 1

[illegible]

END

DATE
FILMED

11-81

DTIC